

ALTUS LIFT TRUCKS LLC

EQUIPMENT CONDITION REPORT

Serial #:	1A257528	Attachment:	NA
Make:	Crown	Tires:	POLY
Model:	SP3040-30	Forks:	42"
Year:	2003	Valves:	NA
Mast (LH/RH):	Triple; 155/366"	Other:	
Capacity (lbs):	3,000	Voltage:	24v
Meter (Hours):	6,472	L X W X H	
Fuel:	Electric	Zone:	
Weight (lbs):	7,483 lb.		

Visual Inspection	
Appearance	Fair
Seat	NA
Floor Plate	Good
Tank Brackets	NA
Steer Wheels & Tires %	80%
Drive Wheels & Tires %	80%
Sheet Metal	Good
Decals	Repair
Operational Checks	
Hour Meter/ Gauges	Good
Work Its/Tail Lts	Good
Engine/Motor Operation	Good
Brake Operation	Good
Park Brake Operation	Good
Steer Operation	Good
Mast Operation	Good
Tilt Operation	Good
Mast Attachments	Good
Accelerator	Good
Trans & Drive Axle	
Universal Joint	NA
Shift Linkage	NA
Oil Leaks	Good

Safety Inspection	
Seat Belts/Restraints	None
Safety Decals	Needs repair
ID Plates	Good
Horn	Good
Strobe/BU Alarm	Good
Overhead Guard	Good
Load Backrest	NA
Engine Compartment	
Hood Latch	NA
Battery & Cables	NA
Oil Leaks	Good
Exhaust System	NA
Engine Mounts	NA
Hydraulics & Mast	
Chain Tension	Good
Chain Wear	Good
Hoses & Sheaves	Good
Hyd. Control Levers	Good
Mast Carriage Fit	Good
Lift & Tilt Cylinders	NA
Hyd. Control Valve	Good
Hyd. Oil Leaks	Good
Forks Visual Inspection	Good

DETAILS FOR REPAIRS NEEDED	
Total	0



Disclaimers: Engine oil not tested or analyzed, engine compression not tested, and batteries not tested unless noted above. Testing is available - please ask your sales representative. Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks, and notes physical damage.

